



BELL 407GXP

FOR SALE

SERIAL NUMBER 54684	MANUFACTURED 2016	LOCATION Nigeria
PRICE \$2,950,000 USD	TOTAL TIME 2,162 Hrs	AVAILABLE Immediately

EQUIPMENT

- | | | |
|----------------------------------|------------------------------|------------------------------|
| • Rotor brake | • Two (2) Fire extinguishers | • Automatic door openers |
| • Anti-collision lights | • 24v Battery | • Boattail equipment shelf |
| • High skid gear | • Emergency floats w/AFCS | • Air conditioning |
| • Utility map light | • First aid kit | • Preflight step handles |
| • Standard soundproofing | • 28 Amp battery | • Foldable maintenance steps |
| • Auxiliary fuel tank provisions | • Dual controls | • Cargo mirror |
| • Inlet barrier filter | • Sliding passenger windows | • Baggage bay protection |
| • Tail rotor pedal lockout | • Pushout windows | |

HIGHLIGHTS

- Utility configuration

INTERIOR

- Standard Utility interior
- Five (5) passenger seats
- 4-point harness
- Floor protectors
- Litter provisions



AVIONICS

• Avionics suite	<i>Garmin G1000H NXi</i>
• Dual NAV/COMM/GPS	<i>Garmin GIA 63H</i>
• Transponder	<i>Garmin GTX 33H</i>
• TCAS	<i>Garmin GTS 800</i>
• ELT	<i>Artex C406N HM</i>
• Radar altimeter	<i>FreeFlight RA-4500</i>
• ADF	<i>Honeywell KR 87</i>
• VHF COMM	<i>Technisonic TFM-138B</i>
• Satellite communication	<i>SkyTrac ISAT-200A</i>
• Underwater locator beacon	<i>Dukane DK120</i>
• Passenger briefing system	<i>PBS 250</i>
• Autopilot	
• Public address	
• Tail rotor camera	<i>Vision 1000</i>
• Loudhailer	<i>NAT</i>

* Aircraft details are based on the information provided and subject to verification during the purchase process



MAJOR COMPONENTS	LIMIT	REMAINING	%
Main rotor hub	2,500	337.5	13.5%
Main rotor mast assembly	2,500	337.5	13.5%
Transmission	4,500		0.0%
Main driveshaft	2,500	481.3	19.3%
Freewheel assembly	3,000		0.0%
Main rotor swashplate	2,500	337.5	13.5%
Tail rotor gearbox	5,000		0.0%
Tail rotor hub assembly	2,500	408.1	16.3%

ENGINES - 250-C47B	LIMIT	REMAINING	%
Impeller	7,500	337.8	4.5%
2000 hour compressor inspection	2,000		0.0%
Turbine assembly	2,000		0.0%

